

Menu


HISTORY FILE MAP for year 2002

REALTIME

PLAYBACK

RECALLED REALTIME

RECALLED PLAYBACK



362.06:47-06:56 33m 1024bps RT data lost due to multiple
362.07:14-07:29 coherency switchings caused by an MSG
362.07:36-07:38 problem at DSS-24. DR G102074 refers.
362.07:55-08:02